




Water Bacteriological Analysis

Client: King Water Company
PO Box 2243
Oak Harbor, WA 98277

Invoice Number: 22-04471
PO Number:
Project Name: DW

Report Date: 3/23/2022
Approved By: 

Sample Information

Date Collected: 3/22/2022
Sample Purpose: Routine Compliance
Sample Type: Post Treatment/Finished Water Sample
Sample Composition: Coliform Samples
Sample Collected by: F. Pedroza
Source Number: 00

Date Received: 3/22/2022
Suitability: Yes
Chlorine Res: 0.15
Repeat:
Repeat Lab #:
Repeat Date:

System Number: 19948

System Name: DRIFTWOOD HEIGHTS ASSOCIATION

Lab #: 17862		Sample: 699 Lehman Dr				
Analyte	Results	Units	Detection Limit	Method	Analyst	Date Analyzed
TOTAL COLIFORM	Satisfactory	/100ml	1	SM_9223B	ER	3/23/2022
E. COLI	Absent	/100ml	1	SM_9223B	ER	3/23/2022

System: **Driftwood Heights**
 Report: March 2022
 Island County
 Source SO 1

System # 19948 X

Hypochlorite Solution Strength 10%
 LIQUID HYPOCHLORITE 12.5%

BLANKS REPRESENT NO TEST

LBS. OF AVAILABLE CHLORINE PER GALLON OF SOLUTION

0.1

QUANTITY OF WATER TREATED

DATE	WELL #1 METER READING	VOLUME	POUNDS	Chlorine			
				Tank size	Gal. Used	Entry mg/L	Distribution mg/L
25	58,366,120			50	2.5	0.2	0.1
1	58,422,800	56,680	472711	50	3.5	0.2	0.12
2	0	0	0	50			
3	0	0	0	50			
4	58,459,080	36,280	302575	50	2.5	0.31	0.2
5	0	0	0	50			
6	0	0	0	50			
7	58,496,000	36,920	307913	50	3	0.36	0.25
8	0	0	0	50			
9	0	0	0	50			
10	0	0	0	50			
11	0	0	0	50			
12	58,565,860	69,860	582632	50	3	0.35	0.3
13	0	0	0	50			
14	58,590,170	24,310	202745	50	4	0.47	
15	0	0	0	50			
16	0	0	0	50			
17	0	0	0	50			
18	58,642,110	51,940	433180	50	4	0.45	0.39
19	0	0	0	50			
20	0	0	0	50			
21	0	0	0	50			
22	58,696,000	53,890	449443	50	4	0.45	0.15
23	0	0	0	50			
24	0	0	0	50			
25	58,736,500	40,500	337770	50	2	0.39	0.26
26	0	0	0	50			
27	0	0	0	50			
28	0	0	0	50			
29	58,795,640	59,140	493228	50	3	0.36	0.221
30	0	0	0	50			
31	0	0	0	50			

429,520

Total pumped for month 429,520
 Average daily usage 14,317
 Average per connection (111) 129

Driftwood Heights 1

Year:

March Apr 2022

Date	Mth/Day	#1 Well Meter	Average Daily Usage	Hour Meters					Generator Hours	Propane Level	Sign
				Line Pressure Main	10th St.	#1 Pump	#2 Pump	Well			
3/11/22		58,432,800	14,170	50	20	17,845.6	7750.4	15,021.1			
3/14/22		58,459,080	12,093	51	76	17,850.7	7751.6	15,021.1			
3/17/22		58,496,000	12,307	48	82	17,856.1	7757.0	15,027.1			
3/22/22		58,505,860	13,972	46	71	17,865.4	7762.7	15,033.0			
3/24/22		58,590,170	12,153	48	73	17,869.1	7765.0	15,035.0	315.0	33%	
3/26/22		58,604,110	12,985	51	70	17,876.6	7761.7	15,031.3			
3/29/22		58,696,000	13,477	52	80	17,884.0	7774.4	15,043.8			
3/31/22		58,736,500	13,500	48	72	17,884.6	7777.9	15,047.1			
3/31/22		58,795,440	14,785	49	80	17,898.1	7783.2	15,052.1			
4/1/22		58,836,340	13,67	50	80	17,903.7	7786.7	15,055.4			

Notes:


3/22/22 Routine BT Sample



Water Bacteriological Analysis

Client: King Water Company
PO Box 2243
Oak Harbor, WA 98277

Invoice Number: 22-04471
PO Number:
Project Name: DW

Report Date: 3/23/2022
Approved By: 

Sample Information

Date Collected: 3/22/2022
Sample Purpose: Routine Compliance
Sample Type: Post Treatment/Finished Water Sample
Sample Composition: Coliform Samples
Sample Collected by: F. Pedroza
Source Number: 00

Date Received: 3/22/2022
Suitability: Yes
Chlorine Res: 0.15
Repeat:
Repeat Lab #:
Repeat Date:

System Number: 19948

System Name: DRIFTWOOD HEIGHTS ASSOCIATION

Lab #: 17862		Sample: 699 Lehman Dr				
Analyte	Results	Units	Detection Limit	Method	Analyst	Date Analyzed
TOTAL COLIFORM	Satisfactory	/100ml	1	SM_9223B	ER	3/23/2022
E. COLI	Absent	/100ml	1	SM_9223B	ER	3/23/2022

System: *Driftwood Heights*
 Report: March 2022
 Island County
 Source SO 1

System # 19948 X

Hypochlorite Solution Strength 10%

LIQUID HYPOCHLORITE 12.5%

BLANKS REPRESENT NO TEST

LBS. OF AVAILABLE CHLORINE PER GALLON OF SOLUTION

0.1

QUANTITY OF WATER TREATED

DATE	WELL #1 METER READING	VOLUME	POUNDS	Chlorine			
				Tank size	Gal. Used	Entry mg/L	Distribution mg/L
25	58,366,120			50	2.5	0.2	0.1
1	58,422,800	56,680	472711	50	3.5	0.2	0.12
2	0	0	0	50			
3	0	0	0	50			
4	58,459,080	36,280	302575	50	2.5	0.31	0.2
5	0	0	0	50			
6	0	0	0	50			
7	58,496,000	36,920	307913	50	3	0.36	0.25
8	0	0	0	50			
9	0	0	0	50			
10	0	0	0	50			
11	0	0	0	50			
12	58,565,860	69,860	582632	50	3	0.35	0.3
13	0	0	0	50			
14	58,590,170	24,310	202745	50	4	0.47	
15	0	0	0	50			
16	0	0	0	50			
17	0	0	0	50			
18	58,642,110	51,940	433180	50	4	0.45	0.39
19	0	0	0	50			
20	0	0	0	50			
21	0	0	0	50			
22	58,696,000	53,890	449443	50	4	0.45	0.15
23	0	0	0	50			
24	0	0	0	50			
25	58,736,500	40,500	337770	50	2	0.39	0.26
26	0	0	0	50			
27	0	0	0	50			
28	0	0	0	50			
29	58,795,640	59,140	493228	50	3	0.36	0.221
30	0	0	0	50			
31	0	0	0	50			

429,520

Total pumped for month 429,520
 Average daily usage 14,317
 Average per connection (111) 129

Driftwood Heights 1

Year:

Mar 4 Apr 20 22

Date	#1 Well Meter	Average Daily Usage	Line Pressure		#1 Pump	Hour Meters		Well	Generator Hours	Propane Level	Sign
			Main	10th St.		#2 Pump	Well				
3/11/22	58,423,800	14,170	50	80	17,845.6	7750.4	15,021.1				
3/14/22	58,459,050	12,053	51	76	17,850.7	7753.6	15,021.1				
3/17/22	58,496,000	12,307	48	82	17,856.1	7757.0	15,021.1				
3/20/22	58,535,800	13,972	46	71	17,865.4	7762.7	15,035.0				
3/24/22	58,590,170	12,155	48	73	17,869.1	7765.0	15,035.0	315.0	33%		
3/28/22	58,642,110	12,985	51	70	17,876.6	7768.7	15,037.2				
3/29/22	58,696,000	13,472	52	80	17,884.0	7774.4	15,043.8				
3/30/22	58,736,500	13,500	48	72	17,889.6	7777.9	15,047.1				
3/31/22	58,795,640	14,185	49	80	17,898.1	7783.2	15,052.1				
4/1/22	58,836,340	13,567	50	80	17,903.7	7786.7	15,055.4				

Notes:

3/29/22 Routine BT Sample

