

## Water Bacteriological Analysis

**174 84969**

**Sample:** 847 Margie Ann Drive  
**Client:** King Water Company  
PO Box 2243  
Oak Harbor, WA 98277

**Invoice Number:** 23-22682  
**PO Number:**  
**Project Name:**  
**Report Date:** 12/27/2023

**Phone:** (360) 678-5336  
**Email:** cerickson@nwnaturalwaterservices.com

**Approved By:** 

### Sample Information

Date Collected:	12/26/2023	Date Received:	12/26/2023
Sample Collected by:	F. Pedroza	Source Number:	0
Sample Purpose:	Routine Compliance	Chlorine Res:	0.42
Sample Type:	Post Treatment/Finished Water Sample		
Sample Composition:	Coliform Samples		
Sample Collection:	Flowing		
Suitability:	Yes		

**System Number: 19948**

**System Name: DRIFTWOOD HEIGHTS ASSOCIATION**

Lab #: 84969		Sample: 847 Margie Ann Drive				
Analyte	Results	Units	Detection Limit	Method	Analyst	Date Analyzed
TOTAL COLIFORM	Satisfactory	/100ml	1	SM_9223B	SJ	12/27/2023
E. COLI	Absent	/100ml	1	SM_9223B	SJ	12/27/2023